

```
=====
=   FIRMWARE VERSION HISTORY   =
=====
=       Radio Explorer         =
=====
=   Deva Broadcast Ltd.       =
=   http://www.devabroadcast.com =
=====
```

Version 01.03.1025 (8-May-2013)

Fixed bug - when edit PI campaign by local interface and restart device "EEPROM Error" is issued in some cases.

Version 01.02.978 (29-Jan-2013)

Fixed bug - not cleared RDS properties after switching External - Internal MPX.

Fixed bug - does not decode RDS from external input if RF level on antenna input is low.

Minor bug fixes.

Version 01.01.897 (18-Oct-2012)

First firmware release for Radio Explorer